

Re: More Best Practices for Engineers

8. Manage time, don't let time manage you.

9) Go easy on the beer at lunch.

10) Let the wire cool off before you clip the scope probe back on it.

11) Don't breadboard. Don't simulate. They just waste time and dilute the excitement.

12) When you're really, really behind schedule, take a break.

13) Avoid machining.

14) Source terminate.

15) Orthogonality is your pal.

16) Ground everything, as many places as possible.

17) You're using too many bypass caps, and you don't have enough test points.

18) Never implement your first idea.

19) Packaging.

John

.