

Re: Buick Rendezvous stops my 2610

Source: <http://sci.tech-archive.net/Archive/sci.geo.satellite-nav/2004-10/1615.html>

From: q (q_at_z.net)

Date: 10/30/04

Date: Sat, 30 Oct 2004 18:58:38 -0400

It's possible that the Buick has a metalized windshield which limits the reception of satellite signals. The fact that the unit received a stronger signal looking out the passenger side window or held outside supports this. Using the external antenna will solve this problem. I use the same antenna with my Jeep Grand Cherokee. The windshield is not metalized and I get decent reception without the external antenna. I did notice, however, that using the external greatly improves the reception. Hope this helps!