Re: Expressing fractions

Source: http://sci.tech−archive.net/Archive/sci.lang/2005−01/0688.html

---

From: Lee Sau Dan (*danlee_at_informatik.uni−freiburg.de*)
Date: 01/05/05

Date: 05 Jan 2005 23:37:38 +0800

>>>>> "Paul" == Paul J Kriha <paul.nospam.kriha@paradise.net.nz> writes:

> Paul> What's more, there is a reason why your ohmmeter will give
> Paul> you misleading resistance figures. Resistance of the
> Paul> metal−hand contact is _voltage_ dependent!!! Your ohmmeter
> Paul> performs the measurement in wrong condition. I guess it has
> Paul> an internal batery of 1.2/1.5V.

This problem can be overcome by using zero−current methods of measuring resistance. I don't know if those cheap electronic multimeters use any current when in resistance measurement modes. Anyone knows?

−−
Lee Sau Dan §õ¦u´° ~{@nJX6X~}
E−mail: danlee@informatik.uni−freiburg.de
Home page: http://www.informatik.uni−freiburg.de/~danlee