

Re: Sourcing an Acrylic / Plexiglas / Perspex / PMMA adhesive

Source: <http://sci.tech-archive.net/Archive/sci.chem/2005-01/0748.html>

From: Marshall Dudley (mdudley_at_king-cart.com)

Date: 01/17/05

Date: Mon, 17 Jan 2005 12:35:56 -0500

I always simply mix a solvent with acrylic, to form a glue with the consistency desired. Once dry, it is pure acrylic, so it forms joints that are clear and darned near as strong as the original acrylic.

However I do not understand the requirement of:

Must be unaffected by long term UV or Sunlight

Since acrylic IS affected by UV and sunlight, why does just the joint have to be not affected?

Marshall

grant wrote:

- > *I am currently trying to source an acrylic adhesive that fulfils the*
- > *following requirements, and I would appreciate any product suggestions.*
- > *Thanks*
- > *Grant*
- >
- > *Requirements:*
- >
- > *1/ Must be structural, very high strength*
- > *2/ Must be gap filling*
- > *3/ Must be clear after setting (no colouration, no bubbles released*
- > *from solvent evaporation)*
- > *4/ Must be unaffected by long term UV or Sunlight*
- > *5/ Must be permanently submersible in water (fresh and sea water)*
- > *6/ UV setting adhesives cannot be used due to nature of the join*
- > *7/ Must not give off extremely noxious vapours on setting*
- > *8/ Must be distributed in Europe*
- > *9/ Easily dispensed would be appreciated*
- >
- > *The product is intended to bond cast, extruded and formed acrylic*
- > *together in a high-pressure, load bearing application. The intention is*
- > *to anneal the acrylic either before bonding or after. (Annealing and*

sci.chem: Re: Sourcing an Acrylic / Plexiglas / Perspex / PMMA adhesive

- > *setting the adhesive at the same time – I would be interested to know*
- > *some opinions on doing this together)*
- >
- > *I have currently tested some products, specific polymer adhesives more*
- > *than general adhesives. I have tested:*
- >
- > *IPS Weld-On #16 – seemed to fulfil the requirements except for the*
- > *bubbles released from the solvent. I have tried cooling the*
- > *solvent-based adhesives to 5deg °C before use to limit the bubbles*
- > *formed, but the result was still unsatisfactory.*
- >
- > *IPS Weld-On #40/42 – has a yellow colour tinge.*
- >
- > *A 'self-mixed' adhesive of Bostik Extrufix with acrylic cuttings*
- > *added to form a paste – seemed to fulfil the requirements except for*
- > *the bubbles released from the solvent.*
- >
- > *Bostik Tensol #3 – From the specification it seemed this would fulfil*
- > *the requirements perfectly, however in use it gives of the most noxious*
- > *vapours.*