

# PC based measurements

**Source:** <http://sci.tech-archive.net/Archive/sci.electronics.basics/2004-07/0279.html>

---

**From:** Indroneel Ganguly (*kundol30\_at\_yahoo.com*)

**Date:** 07/08/04

Date: Thu, 8 Jul 2004 19:25:28 +0200

Hello Everybody,

I am trying to use my PC to measure resistance, capacitance and inductance of the respective components.

I would like to use the parallel or serial port to do it.

Do I need to have a ADC circuit to do it ?

I would appreciate any advice on this.

Thank you,

Indroneel