

sci.electronics.design: Re: Honeywell KFC-225 autopilot – what could cause this failure?

Re: Honeywell KFC-225 autopilot – what could cause this failure?

Source: <http://sci.tech-archive.net/Archive/sci.electronics.design/2004-06/1847.html>

From: Everett M. Greene (mojaveg_at_mojaveg.iwvisp.com)

Date: 06/13/04

Date: Sat, 12 Jun 2004 20:30:56 PST

Peter <nospam@nospam9876.com> writes:

- > *The bottom line is whether servos should burn out, no matter what. The*
- > *KFC-225 has only one processor (I have the schematics) and the*
- > *software didn't appear to crash outright in any of the failures.*

There was some discussion recently in one of the embedded computing newsgroups about damage that can occur if motors aren't driven properly (as in correct waveform, duration, etc.).