

Re: Multiplexing LEDs – calculating resistor value

Source: <http://sci.tech-archive.net/Archive/sci.electronics.design/2006-06/msg04871.html>

- *From:* Rich Grise <richgrise@xxxxxxxxxxx>
 - *Date:* Wed, 28 Jun 2006 19:38:43 GMT
-

On Wed, 28 Jun 2006 05:00:28 -0500, John Fields wrote:

On Tue, 27 Jun 2006 23:32:21 GMT, Rich Grise <richgrise@xxxxxxxxxxx>

....

IOW, a given row wouldn't have to be blanked during the shift register load time.

Where did you read that it does?

In Jonathan Kirwan's post:

"You'd make sure all row drivers were off, to start. Then load in "100010111110100000100000011100000010100010011100" into your column shift register. Then enable row 1. Wait, as appropriate. Disable row 1. Load "100010100000100000100000100010000100100010001000" into your column shift register. Then enable row 2. Wait, ... Etc...."

Cheers!
Rich

.