

Re: 8031 question

Source: <http://sci.tech-archive.net/Archive/sci.electronics.design/2007-02/msg00250.html>

- *From:* Spehro Pefhany <speffSNIP@xxxxxxxxxxxxxxxxxxxxxxxxxxxx>
 - *Date:* Thu, 01 Feb 2007 20:55:13 -0500
-

On 1 Feb 2007 16:26:48 -0800, the renowned "mplanic"
<mplanic@xxxxxxxx> wrote:

On Feb 2, 1:28 am, Spehro Pefhany <speffS...@xxxxxxxxxxxxxxxxxxxxxxxxxxxx>
wrote:

On 1 Feb 2007 14:11:05 -0800, the renowned "mplanic"

<mpla...@xxxxxxxx> wrote:

Hello

I have problem with translating .asm code for 8031 MCU.
Here is the source:

<http://www.badongo.com/file/2142125>

Regards

What do you mean by "translating"?

Do you meant that it won't assemble with some particular assembler you
have?

Best regards,
Spehro Pefhany

--

With ASEM -51 ver 1.3 I get this errors:

Re: 8031 question

disp.asm(89): illegal character

<snippage>

disp.asm(3079): illegal character

Regards

50 errors with the Metalink x-assembler.
Some similar huge number with PseudoSam
TASM -51 reports a divide overflow and exits

People should indicate the assembler in the header, eh?

Best regards,
Spehro Pefhany

—

"it's the network..." "The Journey is the reward"

speff@xxxxxxxxxxxxx Info for manufacturers: <http://www.trexon.com>

Embedded software/hardware/analog Info for designers: <http://www.speff.com>

.