

Re: Current Probes

better

than Tuckers and they're just North of the Portland area in Washington.

www.BellNW.com

We just bought one of the older Tek Current Probes. Don't remember the

Model

number, it's at work.

Robert

I have several of the Tek model 610 (If I remember the # right). All current probes (clamp on type) that I have researched use Hall sensors for DC. If you only need AC, I suggest going with the CT type. The Tek worked great until we went overcurrent on a test. It destroyed three of our four probes! Fried the Hall sensors. I have not been able to find a replacement for the sensor and Tek support says it's not worth fixing! 3* \$600, maybe not worth it to them!!!

TEK "support" has really slipped in the last 10–15 years.
I used to repair P6042 and A6302/6303 current probes while at TEK.
(their probe xfmr's were TEK–made,thus costly and not available elsewhere.)

—
Jim Yanik
jyanik
at
kua.net
.