

## Re: Mitsubishi hum & horiz bar

**Source:** <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-06/2351.html>

---

**From:** sofie ([sofie\\_at\\_olyphen.com](mailto:sofie_at_olyphen.com))

**Date:** 06/29/04

Date: Mon, 28 Jun 2004 22:18:33 -0700

george stringe:

YES, you are probably correct with your diagnosis.

First, check and repair the PS.... could be dry or high esr electrolytics or defective diode, bridge, regulator semiconductors?

Once you get the PS repaired if you are still having vertical deflection problems, then check and/or replace the half a dozen or so electrolytics near and around the vertical output circuitry.

Be certain to check the solder connections near and around the high heat producing parts.

You might want to go to the website for this newsgroup at

<http://www.repairfaq.org/>

there, with some search time, you will find a wealth of repair and safety information.

Good luck with the repair....

--

Best Regards,

Daniel Sofie

Electronics Supply & Repair

-----  
"george stringe" <[annsmg@comcast.net](mailto:annsmg@comcast.net)> wrote in message  
news:2085b87b.0406281819.8709a43@posting.google.com...  
> Mitsubishi CS-2610R tv has loud hum, 3/4 inch wide horiz bar for a  
> picture. Don't have manual, thinking vert module and/or ps?  
>  
> thanks