

sci.electronics.repair: Fluke 79 -- Is rotary switch supposed to turn past last position?

## Fluke 79 -- Is rotary switch supposed to turn past last position?

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-07/0653.html>

---

*From:* Tom Del Rosso (*tdnews01\_at\_att.net.invalid*)

*Date:* 07/07/04

Date: Wed, 07 Jul 2004 13:41:20 GMT

I just discovered that the switch on my Fluke 79 can be turned almost 360 degrees. There is a stop preventing it from going CCW past 'Off' and from turning CW to 'Off', but no stop preventing CW motion past 'Amps'.

Maybe I just never noticed this before? I mean, it doesn't feel broken otherwise, and nothing is rattling around. Do others do this?

--

-Reply in group, but if emailing add 2 more zeros-  
-and remove the obvious-