

Re: Fluke 79 -- Is rotary switch supposed to turn past last position?

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-07/0697.html>

From: dave (alofusblountmaybe_at_alltel.net)

Date: 07/08/04

Date: Wed, 7 Jul 2004 20:30:28 -0400

"Tom Del Rosso" <tdnews01@att.net.invalid> wrote in message
news:44TGc.208650\$Gx4.46368@bgtncs04-news.ops.worldnet.att.net...

> *I just discovered that the switch on my Fluke 79 can be turned almost*
> *360 degrees. There is a stop preventing it from going CCW past 'Off'*
> *and from turning CW to 'Off', but no stop preventing CW motion past*
> *'Amps'.*

>

> *Maybe I just never noticed this before? I mean, it doesn't feel broken*
> *otherwise, and nothing is rattling around. Do others do this?*

>

>

> --

> *-Reply in group, but if emailing add 2 more zeros-*

> *-and remove the obvious-*

>

>

This happens after some years of use. My 77 does that, doesn't seem to be a problem.

dave