

## Mitsubishi HS-541V VCR problem

**Source:** <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-10/1953.html>

---

**From:** Geoff Cohen ([geoff\\_at\\_rce.com.au](mailto:geoff_at_rce.com.au))

**Date:** 10/24/04

Date: Sun, 24 Oct 2004 23:50:24 +1000

I have a Mitsubishi HS-541V which has stopped working.

It feels like the VCR isn't sensing the tape position, as the tape cannot be inserted, and, if the tape is partly inserted when the VCR is off, when powered up it ejects the tape.

I checked the 2 LDR's and the IR LED, and as I don't have a schematic, proceeding further will waste mucho hours without much chance of success.

So unless someone knows of a common fault with this model, and is nice enough to tell me, it's bin it time I guess.

Thanks

.

Cheers from Geoff Cohen (0417 657 465)

R.C.Electronics – [www.rce.com.au](http://www.rce.com.au)

The most abundant elements in the universe  
are Hydrogen and Stupidity