

## Re: Mitsubishi HS-541V VCR problem

**Source:** <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-10/2137.html>

---

**From:** JVC dude ([wilkinsons.hifi\\_at\\_talk21.com](mailto:wilkinsons.hifi_at_talk21.com))

**Date:** 10/26/04

Date: Tue, 26 Oct 2004 19:49:38 +0100

Hi there

What about the mode switch? ~Its the most likely thing to give trouble. you often find cleaning won't cure it since one of the 4 metal wipers has worn away. easy to change, but just watch the timing.

AW Nelson UK

"Geoff Cohen" <[geoff@rce.com.au](mailto:geoff@rce.com.au)> wrote in message  
news:obcnn0ddqufbhere3u9os617ijau452dfc@4ax.com...

> *I have a Mitsubishi HS-541V which has stopped working.*

>

> *It feels like the VCR isn't sensing the tape position, as the tape  
> cannot be inserted, and, if the tape is partly inserted when the VCR  
> is off, when powered up it ejects the tape.*

>

> *I checked the 2 LDR's and the IR LED, and as I don't have a schematic,  
> proceeding further will waste mucho hours without much chance of  
> success.*

>

> *So unless someone knows of a common fault with this model, and is nice  
> enough to tell me, it's bin it time I guess.*

>

> *Thanks*

>

>

>

>

> *Cheers from Geoff Cohen (0417 657 465)*

>

> *R.C.Electronics - [www.rce.com.au](http://www.rce.com.au)*

>

> *The most abundant elements in the universe  
> are Hydrogen and Stupidity*