

Re: Help troubleshooting: Sony STR-D315

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-11/1896.html>

From: CJT (abujlehc_at_prodigy.net)

Date: 11/22/04

Date: Mon, 22 Nov 2004 23:15:35 GMT

Michael wrote:

> *I have a somewhat old Sony STR-D315. The left speaker/headphone*
> *output is sending highly intermittent signals, causing a crackling*
> *sound in both the speaker and headphone.*

>

> *Is there a particular component I can change out to fix this, or*
> *should I just get another receiver. It is probably 8 years old.*

>

> *Thanks,*

>

> *Mike*

>

>

Start with visual inspection. Is it full of dust? Are there cold solder joints? Loose wires?

Exercise the switches and pots and see whether one of them could be the culprit.

Does it behave the same regardless of the input source?

FWIW, I have that same model, so I might be able to help with voltages, etc. if you need any.

--

The e-mail address in our reply-to line is reversed in an attempt to minimize spam. Our true address is of the form che...@prodigy.net.