

Mitsubishi PIP Bypass – Help

Source: <http://sci.tech–archive.net/Archive/sci.electronics.repair/2004–11/2276.html>

From: Joel Elias (*jelia555_at_hotmail.com*)

Date: 11/28/04

Date: Sun, 28 Nov 2004 00:03:45 GMT

My Mitsubishi CS–35601 has a bad PIP board. Replacing all the caps is beyond my level of incompetence, but I think I could handle making a bypass. Searching newsgroups and the web I found a few different configurations for the bypass and I would appreciate some help in making sure I get it right. I pulled the board and found the following identification information.

The part number on the board is 930B552.

There is a paper tag on the board with the ID P05010865

Help in getting this right would be greatly appreciated.

Thanks in advance – Joel