

horizontal line

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-11/2315.html>

From: BigTom (*me_at_my.net*)

Date: 11/28/04

Date: Mon, 29 Nov 2004 00:14:00 +1100

NEC N-4895 tv

I've been reading the sci.electronics.repair faq, and it looks like there's no vertical deflection.

I found 2 caps with high esr/leakage. C453/100uF35v and C458/4.7uF50v and shorted diode D502/RH1S

I need a value for a burnt/open resistor R521.

Is there anything else i should look at? possibly AN5515 ic?

If the ic is faulty can i substitute an AN5521?, i have a spare one out of an old set.