

Re: Mutsubishi cs-26EX1 ,sn# 003704

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-11/2325.html>

From: dkuhajda (rdkuhajda_at_locl_dot_net_at_locl.net)

Date: 11/28/04

Date: 28 Nov 2004 14:27:41 -0800

Start at the PIP module, all the surface mount capacitors will be bad.
Then ESR check all the capacitors in the set, likely you will find 2 to 3
in the vertical output stage, plus a few in the power supply, and a small
assortment across the board.

David