

Re: Electrohome monitor

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2005-03/2026.html>

From: Techforce (*spam_at_linhax.com*)

Date: 03/25/05

Date: Thu, 24 Mar 2005 20:04:32 -0500

Sounds like the internal resistance of your VOM is providing a path to ground enough to activate the secondary HV section of the Flyback xfmr. My diagnosis is a defective flyback xfmr, or a bad solder on the ground for the FBT secondary.

"Mark McGrath" <mark@ems-fife.co.uk> wrote in message
news:be9b8b41.0503241241.107d5879@posting.google.com...
| I have a dead Electrohome monitor on a cnc machine. The model is a
| 38-K421MD-04.
| If I hook a voltmeter on to check the grid voltage and power up the
| monitor works fine. If I power up with the meter disconnected it
| doesn't work.
| Does anyone have any ideas? Does anyone have a schematic?
| regards, Mark.