

Re: Sanyo STK 392 040 Convergence AMP burns out in HDTV application

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2005-04/msg01482.html>

- *From:* Christian Tredal <chris@xxxxxxxxxxxxxxxxxxxxxxxxxxxxx>
 - *Date:* Fri, 22 Apr 2005 11:10:29 +0200
-

Den Thu, 21 Apr 2005 21:28:37 -0500. skrev LB:

> Any reason for this IC to burn out? Replaced carefully, enough heat sink
> grease. Ran one week.
>
> L

Bad caps at it's output. Test with an ESR meter. or simply change them.

--

Med venlig hilsen

Christian Tredal
.

• *References:*

- ◆ *Sanyo STK 392 040 Convergence AMP burns out in HDTV application*
 - ◇ *From:* LB
- Prev by Date: *Re: Password remove on Tecra 8000*
- Next by Date: *Re: DVD recorders*
- Previous by thread: *Sanyo STK 392 040 Convergence AMP burns out in HDTV application*
- Next by thread: *Re: Sanyo STK 392 040 Convergence AMP burns out in HDTV application*
- Index(es):
 - ◆ *Date*
 - ◆ *Thread*