

Re: Yoke Replacement

Source: <http://sci.tech--archive.net/Archive/sci.electronics.repair/2005-06/msg00429.html>

- *From:* "Art" <plotsligt@xxxxxxxxxxxxx>
 - *Date:* Wed, 8 Jun 2005 07:45:40 -0400
-

Congrats Gov.

"Chris F." <zappymanREMOVETHIS@xxxxxxxxxxxxx> wrote in message
[news:kGhpe.43397\\$Ph4.1035485@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:news:kGhpe.43397$Ph4.1035485@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx)
> Set fixed! I simply connected the H winding from another yoke in series,
> and
> everything seems to work great. Now I just have to find a remote that will
> adjust the color/brightness/etc, and the set is ready to use.
> Thanks for your help.
>
> "Doug" <dmac1054@xxxxxxxxxxxxxxxxxxxxx> wrote in message
> news:1118018702.248068.38170@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx
>> What brand and model is this set?
>> Doug
>>
>
>

• *References:*

- ◆ ***Yoke Replacement***
 ◇ *From:* Chris F.
 - ◆ ***Re: Yoke Replacement***
 ◇ *From:* Remove _ for valid address
 - ◆ ***Re: Yoke Replacement***
 ◇ *From:* Doug
 - ◆ ***Re: Yoke Replacement***
 ◇ *From:* Chris F.
-
- Prev by Date: ***Re: Power Supply Sony KV32S12***
 - Next by Date: ***Re: Fixed : PTK169 B+ still high***
 - Previous by thread: ***Re: Yoke Replacement***
 - Next by thread: ***Coby DVD-224 Progressive scan dvd/cd/mp3 player No power problem Fixed***
 - Index(es):
 - ◆ ***Date***
 - ◆ ***Thread***