

Re: Let talk: TN50X81 (chassis TAC9960), convergence stuff

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2005-06/msg00465.html>

- *From:* dkuhajda@xxxxxxxxx
 - *Date:* 8 Jun 2005 17:43:16 -0700
-

IC? Most convergence module failures I have seen were due to the surface mount capacitors. If it has then, ESR all of them before replacing any ics.

- *Follow-Ups:*
 - ◆ ***Re: Let talk: TN50X81 (chassis TAC9960), convergence stuff***
 - ◇ *From:* Jason D.
- *References:*
 - ◆ ***Let talk: TN50X81 (chassis TAC9960), convergence stuff***
 - ◇ *From:* Jason D.
- *Prev by Date:* [*Panasonic 36sx31e degauss circuit problems*](#)
- *Next by Date:* [*Sony KP57HW42*](#)
- *Previous by thread:* [*Let talk: TN50X81 \(chassis TAC9960\), convergence stuff*](#)
- *Next by thread:* [*Re: Let talk: TN50X81 \(chassis TAC9960\), convergence stuff*](#)
- *Index(es):*
 - ◆ [*Date*](#)
 - ◆ [*Thread*](#)