

# SONT KV-27S10

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2005-06/msg01486.html>

---

- *From:* [avitechelectronics@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:avitechelectronics@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx) (darren)
  - *Date:* Tue, 28 Jun 2005 00:17:42 -0000
- 

this TV originally had no power, the H-output and 2 power transistors had been changed to repair the power, however now the TV turns on, but the while picture has been shifted up, no retrace.. vert IC output has been changed, along with steering diode, and pump-up capacitor, still no change

anyone have any ideas ?

.

---

- *Follow-Ups:*
  - ◆ [re:SONT KV-27S10](#)
    - ◇ *From:* darren
- Prev by Date: [Re: can join Bi-amp signal to normal \(single terminal\) speakers?](#)
- Next by Date: [re:Help...Sony KV32S20 won't turn on](#)
- Previous by thread: [Re: AVOMeter compared to cheap modern digital meter](#)
- Next by thread: [re:SONT KV-27S10](#)
- Index(es):
  - ◆ [Date](#)
  - ◆ [Thread](#)