

Re: VPH05

Source: <http://sci.tech--archive.net/Archive/sci.electronics.repair/2005-07/msg00528.html>

- *From:* "tibou64" <chrisdore@xxxxxxxxx>
 - *Date:* Wed, 06 Jul 2005 07:17:26 -0400
-

I was saying in my post in french that i was interested in getting the information he was speaking about because i have a XC3725C mitsubishi display that needs to be fixed. I wanted to know more about the VPH03 that he used to replace his VPH, where to buy it... and asked him to send me the datasheets.

If it can help, it seems that SONY has a VPH05B IC that is easier to find than the VPH05 from SANYO or Mitsubishi and can do the job. The service center, repaired the damage VPH05 using a VPH05B from Sony...

bye

• *References:*

- ◆ **[Re: VPH05](#)**
 - ◇ *From:* tibou64
 - ◆ **[Re: VPH05](#)**
 - ◇ *From:* Inty
 - ◆ **[Re: VPH05](#)**
 - ◇ *From:* NSM
-
- Prev by Date: **[Re: VPH05](#)**
 - Next by Date: **[Re: Power transformer for stereo - shorted - why?](#)**
 - Previous by thread: **[Re: VPH05](#)**
 - Next by thread: **[Alpine car amp model:3548](#)**
 - Index(es):
 - ◆ **[Date](#)**
 - ◆ **[Thread](#)**