

# Re: RCA CTC 203 32" T.V.

---

*Source:* <http://sci.tech--archive.net/Archive/sci.electronics.repair/2005-10/msg01386.html>

---

- *From:* "dkuhajda@xxxxxxxx" <dkuhajda@xxxxxxxx>
  - *Date:* 21 Oct 2005 18:33:53 -0700
- 

Skype\_man wrote:

> Flyback was arcing badly, replaced, works, & looks perfect,  
> but momentarily shuts off, & right back on, even before you  
> can look back at the set. may work for hours, or happen twice  
> in a half hour. Unplugged the customer controls on top of the set,  
> to make sure the "tact" switches aren't "leaky". Anything common  
> here? Nothing on the Thomson B2B website. Sky.

Google groups search here for the ctc203 chassis.

Find the base driver coil that it seems you missed which is very common.

.

---

- *Follow-Ups:*

- ◆ *Re: RCA CTC 203 32" T.V.*  
    ◇ *From:* Jason D.

- *References:*

- ◆ *RCA CTC 203 32" T.V.*  
    ◇ *From:* Skype\_man

- Prev by Date: *RCA CTC 203 32" T.V.*
- Next by Date: *Re: Tinkering with a sick LCD...*
- Previous by thread: *RCA CTC 203 32" T.V.*
- Next by thread: *Re: RCA CTC 203 32" T.V.*
- Index(es):
  - ◆ *Date*
  - ◆ *Thread*