

Re: Coil beyond repair?

Source: <http://sci.tech--archive.net/Archive/sci.electronics.repair/2005-10/msg01647.html>

- *From:* Sam Goldwasser <sam@xxxxxxxxxxxxxxxxxxxxxx>
 - *Date:* 27 Oct 2005 12:57:15 -0400
-

"Dave D" <dave_d@xxxxxxxxxxx> writes:

> "Sam Goldwasser" <sam@xxxxxxxxxxxxxxxxxxxxxx> wrote in message
> news:6wk6fzrp7s.fsf@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxx
>>
>> Replace the mainboard. Not worth the time and agony.
>>
>
> Absolutely agreed.
>
> Apart from the time and effort required for a repair, would anyone in their
> right mind want to chance their CPU in that motherboard? I know I wouldn't!
> Apart from all the leaking, bulging caps and possible electrolyte damage to
> the board, the burned coils suggests the switching regulator fets could be
> shorted. The CPU would be fried pretty quickly if that's the case.

May already be fried.....

--- sam | Sci.Electronics.Repair FAQ: <http://www.repairfaq.org/>
Repair | Main Table of Contents: <http://www.repairfaq.org/REPAIR/>
+Lasers | Sam's Laser FAQ: <http://www.repairfaq.org/sam/lasersam.htm>
| Mirror Sites: http://www.repairfaq.org/REPAIR/F_mirror.html

Important: Anything sent to the email address in the message header above is ignored unless my full name is included in the subject line. Or, you can contact me via the Feedback Form in the FAQs.

• *References:*

- ◆ ***Coil beyond repair?***
 ◇ *From:* Rikard Bosnjakovic
- ◆ ***Re: Coil beyond repair?***
 ◇ *From:* kip
- ◆ ***Re: Coil beyond repair?***
 ◇ *From:* Sam Goldwasser

Re: Coil beyond repair?

- Prev by Date: ***Re: unit hums loudly regardless of volume***
- Next by Date: ***Re: Viewsonic G810 Focus Problem***
- Previous by thread: ***Re: Coil beyond repair?***
- Next by thread: ***Re: Mikroelektronik DL000D***
- Index(es):
 - ◆ ***Date***
 - ◆ ***Thread***