

Re: Sony PVW-2600 format question.

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2005-12/msg01780.html>

- *From:* Vic Thomas <vic@xxxxxxxx>
 - *Date:* Tue, 27 Dec 2005 20:37:49 +0000
-

"David Farber" <farberbear.unspam@xxxxxxx> wrote:

>I received this Sony PVW-2600 in for repair with the complaints of no video,
>audio plays too fast. The machine looks like it has hardly been used. The
>only beta tapes I have were recorded back in the 80's and were recorded in
>either beta II or beta III format. I tried those tapes and it does play too
>fast with no video display. Cleaning the stationary control(?) head didn't
>help. Does this machine have the capability to play back those beta II,
>III, tapes or should I ask the owner for some sample tapes?

PVW machines are not beta-MAX they are beta-CAM which is a broadcast standard component recording format. If there was a fault causing those symptoms you would be getting error messages (it is a sophisticated machine), sounds like your customer is trying to play beta max tapes - it's not going to happen.

Vic Thomas
.

- *References:*
 - ◆ *Sony PVW-2600 format question.*
◇ *From:* David Farber
- Prev by Date: *Need JVC RX317TN Users Manual*
- Next by Date: *Double Images (Ghosting) in Sony TV*
- Previous by thread: *Sony PVW-2600 format question.*
- Next by thread: *Quantum DLT 7000 Problems*
- Index(es):
 - ◆ *Date*
 - ◆ *Thread*