

## Re: Magnavox FP5230 repair

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-01/msg01910.html>

---

- *From:* Adam Preble <[rockobonaparte@xxxxxxxxxxx](mailto:rockobonaparte@xxxxxxxxxxx)>
  - *Date:* Thu, 26 Jan 2006 05:13:59 GMT
- 

Second response since I've looked into replacing these parts. I can get a replacement flyback transformer supposedly for \$81.70 at PartseStore.com

<http://www.partstore.com/ModelDetail.aspx?PageState=1&MfgID=148&ModelID=168744>

It fits my television model perfectly, but I don't know if that's T900. There's one for \$74 also; what do I use?

Q906 is a D1556, with "4E" printed on it in smaller letters. Discarding the 4E, I can get a replacement NTE2331 for ~\$6. The fuseable resistor should be easy enough to find locally. Maybe I can get this all locally--anybody know good parts places in Austin, TX? Just thought I'd ask.

I see the transistor is used for horizontal deflection. So would that explain the lack of display right there? What about vertical?

Given that fuseable resistor and that transistor are burnt, what else should I consider replacing?

.