

# The Famous Plasma Black Line

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-03/msg00855.html>

---

- *From:* [adam8ants@xxxxxxxxxx](mailto:adam8ants@xxxxxxxxxx)
  - *Date:* 12 Mar 2006 14:49:08 -0800
- 

I have a SONY plasma TV. It's developed a problem – a thin horizontal black line that goes from one end of the screen to the other (about 4" from the top of the screen). I've also noticed that several other people have reported the same problem. I've even seen folks selling their plasma TVs on ebay with this same problem.

The bad news is that I am told by service technicians that the problem is a bad display driver board, which is part of the display panel.  
Cost to repair: \$2,000.

My gut tells me it's a bad chip somewhere. I shouldn't have to replace the entire display. Correction – I shouldn't have to throw a \$4,000 tv in the garbage after three years.

Does anyone know how to really fix this problem. My model is KZ-32TS1U.

Thanks,  
AABob

.