

# Denon Receiver Model AVR-3300

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-07/msg00169.html>

---

- *From:* "lun0" <[ola@xxxxxxxxxx](mailto:ola@xxxxxxxxxx)>
  - *Date:* Wed, 5 Jul 2006 12:27:58 -0500
- 

On this model the cooling fan never comes on. It appears to have had the modification already applied that this model was infamous for already. No voltage is ever present to fan. Any help greatly appreciated.

-----= Posted using GrabIt =-----  
-----= Binary Usenet downloading made easy =-----  
--= Get GrabIt for free from <http://www.shemes.com/> =--