

# Re: Sony KVC2983

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-10/msg00296.html>

---

- *From:* Patrick Craenen <[ttl@xxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:ttl@xxxxxxxxxxxxxxxxxxxxxxxxxxxx)>
  - *Date:* Tue, 03 Oct 2006 16:38:08 GMT
- 

On Thu, 21 Sep 2006 13:22:16 +0000, Patrick Craenen wrote:

Hi,

I have a problem with a Sony KVC2983E.  
When I start the set it takes 5 minutes or more before the picture appears, normally this takes 30sec or so. All tips welcome

Greetings,  
Patrick

The problem was fixed by replacing the the tuner (BTP-EC411) with the equivalent Philips UV916H tuner.

Thanks for the feedback  
Best regards,  
Patrick Craenen