

Re: Bob Parker ESR Meter

Source: <http://sci.tech--archive.net/Archive/sci.electronics.repair/2006-11/msg01627.html>

- *From:* Jim Yanik <jyanik@xxxxxxxx>
 - *Date:* 28 Nov 2006 00:53:04 GMT
-

Andrew Tweddle <sarason_not_me@xxxxxxxxxxxxxxxxxxxx> wrote in [news:456b7e31\\$1_1@xxxxxxxxxxxxxxxxxxxx](news:456b7e31$1_1@xxxxxxxxxxxxxxxxxxxx):

My trusty meter is no longer trusty!
It's display values wonder all over the place, the 9V battery is okay
Any ideas? and also a circuit diagram on the web, mine has long since
been misplaced.

Andrew

Bad leads or worn jacks/plugs? Loose nut on the jacks? Bad solder joint at
PCB or at jacks?

Maybe the ESR meter's caps have bad ESR? ;-)

(ironic humor,folks)

--
Jim Yanik
jyanik
at
kua.net
.