

Re: Any Sony TV gurus out there?

## Re: Any Sony TV gurus out there?

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-12/msg00772.html>

---

- *From:* Ray Carlsen <rr0cc@xxxxxxxxxx>
  - *Date:* Tue, 12 Dec 2006 16:35:40 -0800
- 

>>Model KV36FS320 Chassis SCC-S61R-A fails to come on when the power button  
>>is pressed, no relay click, just nine flashes of the Timer/Standby LED.

Possibly a leaky Q605 or D690 in the zero crossing detector.

Leonard,

Thanks for the feedback. I looked at the Z det circuit and there is a nice clean pulse going into the M board. Any problems on that plug-in card have to be a -real- grunt... can't get to half of it while it's running. Perhaps Sony is right: Board replacement. <barf>

Ray

--

My return addy is spamblocked. To reply, remove the zeroes.

.