

Re: Sony laser questions

Source: <http://sci.tech--archive.net/Archive/sci.electronics.repair/2007-03/msg01057.html>

- *From:* blackevilweredragon@xxxxxxxxxx
 - *Date:* 21 Mar 2007 08:08:19 -0700
-

Good, so I can put my mind at ease... lol

I forgot to mention in the original post of mine, the first CD I tried, the one that spun backwards, was a printed music CD (real CD).. And the game CD that froze at a certain audio track was a CD-R..

being the CD-R game was super sensitive, im wanting to give it the benefit of the doubt it was because it was a CD-R, though I used a special type of "mastering" CD-R, ones the music industry use, and would think the KSS240a would atleast have no problem with those...

On Mar 21, 10:54 am, "Arfa Daily" <arfa.da...@xxxxxxxxxxxxxx> wrote:

<blackevilweredra...@xxxxxxxxxx> wrote in message

news:1174488082.039524.68600@xx

Ok, thanks for the information..

Since I did mess with the POTs, and they are probably 1-3 degrees off a little, will this cause major problems in the long run? Right now it seems to work at the moment, as long as the CD is spotless...

As long as it is working at the moment, it is unlikely that you have done any long term damage. Although the settings of the pots are quite critical (two of them are in the tracking and focus servos, and one is the laser power pot as I recall) a few degrees from their original set positions, should not be anything to worry about

Arfa