

Goodmans AM/FM tuners.

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2007-03/msg01115.html>

- *From:* "Dave Plowman (News)" <dave@xxxxxxxxxxxxxxxx>
 - *Date:* Thu, 22 Mar 2007 13:44:55 +0000 (GMT)
-

In case anyone was pondering hard on the question and about to reply, don't bother – it's sorted. ;-)

Turned out to be a fault in the VCO power supply – the same cap had failed in each one.

—

*I will always cherish the initial misconceptions I had about you

Dave Plowman dave@xxxxxxxxxxxxxxxx London SW
To e-mail, change noise into sound.

.