

Re: Sony KV-27HFR – Bad Tuner?

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2007-07/msg00197.html>

- *From:* "Chris F." <zappymanNOSPAM@xxxxxxxxxxx>
 - *Date:* Thu, 5 Jul 2007 11:26:35 -0300
-

I will give that a try, thanks.

"Leonard Caillouet" <nospam@xxxxxxxx> wrote in message
[news:Jp4ji.8850\\$Zt6.8640@xxxxxxxxxxxxxxxx](mailto:news:Jp4ji.8850$Zt6.8640@xxxxxxxxxxxxxxxx)

Have you tried resoldering the bad joints in the IF block? Very common on these units.

Leonard

"Chris F." <zappymanNOSPAM@xxxxxxxxxxx> wrote in message
[news:468bdb70\\$0\\$4338\\$9a566e8b@xxxxxxxxxxxxxxxx](mailto:news:468bdb70$0$4338$9a566e8b@xxxxxxxxxxxxxxxx)

This may be a toughie.... the set will tune in a station but will not lock on, it just drifts back and forth, alternating between a picture and snow. I replaced all the caps in the tuner section and it made no difference. I can't locate a pre-scaler IC (which I've seen go bad on other sets), so I'm assuming it's built into the tuner itself. Am I looking at a bad tuner at this point? (Part# 1-463-771-11)
I'd normally junk anything needing a tuner, but this set just has too nice a picture to give up on it.
Thanks for any advice.

—

To reply via Email, remove NOSPAM from the address