

# Laptop LCD is only half lit after CCFL repair...

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2008-06/msg00026.html>

---

- *From:* [Shnuck93@xx](mailto:Shnuck93@xx) (Shnuck)
  - *Date:* Mon, 02 Jun 2008 10:42:57 -0500
- 

Hi all:

I have an T43 Thinkpad whose LCD had been slowing dying (took on a pinkish hue until eventually the screen went dim)—I had diagnosed this as a problem with either the backlight or the inverter.

So, I replaced the CCFL (yes, I realize replacing the inverter would have been an easier way to find out which part actually died, but, oh well). My LCD now has a band of brightness on the bottom of the screen...and only on the bottom. The rest of the screen is still quite dark. My question is: does this mean I replaced the CCFL incorrectly? or is the inverter true root of the problem?

.