

Re: Mystery Mountain Meteorite Malady

Source: <http://sci.tech-archive.net/Archive/sci.space.history/2007-09/msg00439.html>

- *From:* Rick Jones <rick.jones2@xxxxxx>
 - *Date:* Wed, 19 Sep 2007 23:34:35 +0000 (UTC)
-

Pat Flannery <flanner@xxxxxxxxxx> wrote:

The color stills just before impact show some flames back at the exhaust, but they are only going a couple feet behind the rocket, so it looks like thrust was pretty much terminated by the time of impact.

If the rocket was going (mostly) straight down, unless the tanks were pressurized, or they had drains at the top, I guess it stands to reason that thrust would have terminated no?

rick jones

—

portable adj, code that compiles under more than one compiler
these opinions are mine, all mine; HP might not want them anyway... :)
feel free to post, OR email to rick.jones2@hp.com but NOT BOTH...

.