

# heat shield

---

*Source:* <http://sci.tech-archive.net/Archive/sci.space.shuttle/2007-06/msg00296.html>

---

- *From:* [john2375@xxxxxxxxxxx](mailto:john2375@xxxxxxxxxxx)
  - *Date:* Sun, 17 Jun 2007 15:51:23 -0700
- 

wasn't there a protruding gap=filler near the landing gear door that they were going to take care of? Did they already or not? All I hear them talk about is the thermal blanket on the back that they said was not really all that serious...

.