

Tinning a solid copper bar.

Source: <http://sci.tech-archive.net/Archive/sci.electronics.basics/2007-05/msg01209.html>

- *From:* eromlignod <eromlignod@xxxxxxx>
 - *Date:* 29 May 2007 11:46:12 -0700
-

Hi guys:

I'd like to tin one side of a 5/16" square copper bar so that it can be soldered to a PCB. A soldering iron isn't doing the trick, even with lots of flux. Any ideas?

Don

.