

Multilayer toriadal transformer windings

Source: <http://sci.tech-archive.net/Archive/sci.electronics.design/2008-03/msg03253.html>

- *From:* Jason <bennett.jason@xxxxxxxxxx>
 - *Date:* Tue, 18 Mar 2008 22:17:20 -0700 (PDT)
-

What problems/disadvantages occur if:

- 1) some winds aren't close beside one another?
- 2) winding clockwise & a wind (single loop) goes anti-clockwise back lapping?

Thanks in advance for any help :)

.