

Pace desolder station

Source: <http://sci.tech-archive.net/Archive/sci.electronics.misc/2004-07/0609.html>

From: Mjolinor (mjolinor_at_hotmail.com)

Date: 07/26/04

Date: Mon, 26 Jul 2004 09:12:09 GMT

Anyone got one and can you tell me about the wire that goes from the 2 volt 50 amp unit to the tweezers. I ripped it to bits and the connections inside are silver soldered not soft soldered and it seems that no matter what I use unless it is basically copper bars it gets really hot. The plugs on the wire are very similar to UHF/VHF coax plugs (not F type) and I can't see that they would carry the current. It's difficult trying to make one when I have never seen one and the chance of finding one seem to be pretty low.