

## Re: white Line

**Source:** <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-10/1514.html>

---

**From:** Jacques Carrier ([jcarrier\\_at\\_collegeem.qc.ca](mailto:jcarrier_at_collegeem.qc.ca))

**Date:** 10/18/04

Date: 18 Oct 2004 10:28:24 -0700

Here is the method suggested:

- 1)Resolder the vertical section (IC,Caps and resistors)
- 2)Replace all the caps used in the vertical section.
- 3)Replace the vertical IC if the problem persists.

Good luck.

Jacques