

Hitachi VT-FX523A(S) Fuse

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2004-12/1857.html>

From: SanchoPanza (*grayghost1_at_aol.com*)

Date: 12/17/04

Date: 16 Dec 2004 17:31:04 -0800

Hello. I have a Hitachi VT-FX623A(S) which is about 5 years old. It recently stopped working. Basically, it stopped working when no one was around. The lights won't even come on. No display. No lights.

I've opened the device and noticed that the fuse (3A 250V) is blown. I've tried replacing the fuse but each time after replacing the fuse, when I plug in the VCR the fuse just burns out again. Does anyone have experience they're willing to share about this?