

sci.electronics.repair: Re: I killed my Hitachi 28" widescreen ;-(

Re: I killed my Hitachi 28" widescreen ;-(

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2005-01/2550.html>

From: Jerry G. (jerryg50_at_hotmail.com)

Date: 01/21/05

Date: 21 Jan 2005 09:50:40 -0800

This can be anything that you did. You may have bridged some traces or connections, or didn't properly solder some of them. If you made any bridged connections or created a critical opened connection, there is a chance that some other components have been damaged.

If you are not experienced at TV servicing, your best bet would have to bring the set in to a service center to have it serviced in the first place. The repair may have not been too expensive to start with.
Jerry G.

=====