

Re: Bad tuner?

Source: <http://sci.tech--archive.net/Archive/sci.electronics.repair/2005-06/msg00992.html>

- *From:* Tom MacIntyre <tom__macintyre@xxxxxxxxxxxx>
 - *Date:* Fri, 17 Jun 2005 22:09:07 GMT
-

On Fri, 17 Jun 2005 21:37:51 GMT, Tom MacIntyre
<tom__macintyre@xxxxxxxxxxxx> wrote:

>On 17 Jun 2005 03:13:33 -0700, stokesb@xxxxxxx wrote:

>

>>Thanks Ron, I'll see if I can find a datasheet for this to learn more
>>about this IC. I'm guessing you mean it's a bitch to replace due to
>>it's size? Any idae what the component costs?

>

>It's the position...you have to cut pins on the IC, etc., to get it
>out, and too much heat can easily ruin some solder pads...if I
>remember correctly.

>

>Tom

Hmmm...double-sided solder also?

Tom

.

- *References:*

- ◆ ***Bad tuner?***
 - ◇ *From:* stokesb
- ◆ ***Re: Bad tuner?***
 - ◇ *From:* BongBoy
- ◆ ***Re: Bad tuner?***
 - ◇ *From:* James Sweet
- ◆ ***Re: Bad tuner?***
 - ◇ *From:* RonKZ650
- ◆ ***Re: Bad tuner?***
 - ◇ *From:* stokesb
- ◆ ***Re: Bad tuner?***
 - ◇ *From:* Tom MacIntyre

- Prev by Date: ***Re: Bad tuner?***
- Next by Date: ***Re: Bad tuner?***
- Previous by thread: ***Re: Bad tuner?***

Re: Bad tuner?

- Next by thread: **Re: Bad tuner?**
- Index(es):
 - ◆ **Date**
 - ◆ **Thread**