

Re: Sony DVP S300 – distorted pic and sound

Source: <http://sci.tech–archive.net/Archive/sci.electronics.repair/2006–01/msg01722.html>

- *From:* "RichK" <me@xxxxxxx>
 - *Date:* Mon, 23 Jan 2006 14:19:59 –0500
-

Thanks Mark,

Will do some fishing around the board. Just wanted to be in the right pond :-)

Would not bother to replace the laser, but a bad cap may be economical to replace if I find it.

Regards,

Rich

"Mark D. Zacharias" <spammenot@xxxxxxxxxxxxx> wrote in message

- > I dunno – we do see lots of laser pickups bad, but if it continues to play
- > through the disc, the main board could be bad. Not much you can really do
- > to
- > troubleshoot; either replace the pickup and hope that fixes it, or if that
- > doesn't fix it, start looking closer at the board – maybe a capacitor
- > leaking for example.
- >
- > Obviously – the problem is cost. A new player is cheaper than a
- > replacement
- > pickup, and cheaper by far than the board.
- >
- > Welcome to the exciting world or electronic repair!

• *References:*

- ◆ ***Sony DVP S300 – distorted pic and sound***
 ◇ *From:* RichK
- ◆ ***Re: Sony DVP S300 – distorted pic and sound***
 ◇ *From:* Michael Kinnaird
- ◆ ***Re: Sony DVP S300 – distorted pic and sound***

Re: Sony DVP S300 – distorted pic and sound

◇ *From:* Mark D. Zacharias

- Prev by Date: ***Re: Microwave – fuse?***
- Next by Date: ***Re: Linksys router wall wart?***
- Previous by thread: ***Re: Sony DVP S300 – distorted pic and sound***
- Next by thread: ***Magnavox FP5230 repair***
- Index(es):
 - ◆ ***Date***
 - ◆ ***Thread***