

Re: Sony MDP-500 Laserdisc shutdown problem.

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-01/msg01884.html>

- *From:* "Charon" <ebauld@xxxxxxxxxx>
 - *Date:* 25 Jan 2006 14:27:59 -0800
-

I was working on this with him, and you mention moving the lazer to the out edge by hand. I remember clearly while working on it the lazer was allready at the far outside edge of the player. And it did not appear to be able to travel any futher. Im going to guess here and say that the lazer should not be at rest at the far outside edge of the disc then ?

.

- *Follow-Ups:*
 - ◆ *Re: Sony MDP-500 Laserdisc shutdown problem.*
 - ◇ *From:* Charon
- *References:*
 - ◆ *Sony MDP-500 Laserdisc shutdown problem.*
 - ◇ *From:* littlesureshot
 - ◆ *Re: Sony MDP-500 Laserdisc shutdown problem.*
 - ◇ *From:* Jumpster Jiver
- Prev by Date: *Re: Repair method*
- Next by Date: *Re: 3 phase to single*
- Previous by thread: *Re: Sony MDP-500 Laserdisc shutdown problem.*
- Next by thread: *Re: Sony MDP-500 Laserdisc shutdown problem.*
- Index(es):
 - ◆ *Date*
 - ◆ *Thread*