

# Re: Denon 3801 Dropped Digital Audio

---

*Source:* <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-06/msg01635.html>

---

- *From:* "Mark D. Zacharias" <[spammenot@xxxxxxxxxxxxx](mailto:spammenot@xxxxxxxxxxxxx)>
  - *Date:* Thu, 29 Jun 2006 08:28:39 GMT
- 

"Arfa Daily" <[arfa.daily@xxxxxxxxxxxxx](mailto:arfa.daily@xxxxxxxxxxxxx)> wrote in message  
[news:5MLog.20637\\$OT.17483@xxxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:news:5MLog.20637$OT.17483@xxxxxxxxxxxxxxxxxxxxxxxxxxxxx)

"Douglas Fifield" <[douglas.fifield@xxxxxxxxxxxxx](mailto:douglas.fifield@xxxxxxxxxxxxx)> wrote in message  
[news:j076a2p89p3er6tabblq8rauhnlam6u7o@xxxxxxxxxxxxx](mailto:news:j076a2p89p3er6tabblq8rauhnlam6u7o@xxxxxxxxxxxxx)

All,

DVD audio suddenly stopped working on my Denon 3801. Still get sound through analog connections from VCR. Replaced DVD player without change in digital audio behavior.

Stumped and looking for advice.

Douglas

Coaxial connection or optical ?

Arfa

Seen bad solder connections on the various chips on the DSP board. Not for the Do-it-your-self-er. There are hundreds of solder connections potentially involved (surface-mounted IC's). I have seen resoldering fix various problems like this. Denon does not sell boards for the most part.

Mark Z.