

Re: Computer grounding via a UPS not proper – what could be the problem.

Re: Computer grounding via a UPS not proper – what could be the problem.

Source: <http://sci.tech-archive.net/Archive/sci.electronics.repair/2006-08/msg00576.html>

- *From:* Vivek.M <vivekm1234@xxxxxxxxxxxxxxxx>
 - *Date:* Thu, 03 Aug 2006 20:24:40 +0530
-

Many thanks you guys! I have isolated the problem and it is in the UPS. I also spoke to my Dad and he said that he had this problem before, and the tech had changed a MOV (apparently Dad had the good-sense to ask – it's apparently a fairly common problem.) Sorry for the delay in replying and leaving the thread hanging!

.